

Program Notice

FGIS-PN-03-03

September 5, 2003

WALK-THROUGH SAFETY INSPECTIONS AT GRAIN ELEVATORS

Contents

1.PURPOSE	2
2.EFFECTIVE DATE	2
3.BACKGROUND	2
4.POLICY	2
5. QUESTIONS	3

The U.S. Department of Agriculture (USDA) prohibits discrimination in its programs on the basis of race, color, national origin, sex, religion, age, disability, political beliefs, and marital or familial status. (Not all prohibited bases apply to all programs.) Persons with disabilities who require alternate means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD).

To file a complaint, write to the USDA, Office of Civil Rights, Room 326-W, 1400 Independence Avenue, SW, Washington, DC 20250-9410, or call (202) 720-5964 (voice and TDD). USDA is an equal employment opportunity employer.

1. PURPOSE

The purpose of this notice is to clarify the Federal Grain Inspection Service (FGIS) policy regarding walk-through safety inspections at grain elevators.

2. EFFECTIVE DATE

This action is effective upon receipt

3. BACKGROUND

It is FGIS policy to provide a safe and healthful work environment for all its employees, and to eliminate employee exposure to existing and potentially hazardous working conditions. Accordingly, FGIS employees routinely conduct walk-through safety inspections at grain elevators where FGIS provides onsite service. The purpose of these inspections is to identify and correct hazardous conditions in a timely manner.

4. POLICY

- a. FGIS representatives¹, designated by the local field office manager, must conduct walk-through safety inspections at grain elevators served by the local field office, at least once during each workday; i.e., a day in which FGIS employees are providing onsite inspection/weighing services at the elevator.
- b. During walk-through inspections, the grain elevators must be checked for those conditions that may pose a safety risk to FGIS personnel, including:
 - (1) Fires (including persons smoking), smoldering grain, or visible smoke,
 - (2) Toxic chemical spills,
 - (3) High concentrations of suspended or accumulated dust,
 - (4) Welding, torch cutting, or other hot work,
 - (5) Compressed air being used to remove dust from walls and other areas,
 - (6) Bearings on bucket elevators running hot, slipping belts, and choked legs,
 - (7) Unapproved electrical equipment, loose or damaged electrical conduits, frayed wires, and electrical sparking, and
 - (8) Hazardous walkways, inadequate lighting, defective ladders and stairs, missing guard rails, blocked stairways, and any other potentially hazardous condition.

¹ FGIS supervisor, collateral duty safety and health officer, agricultural commodity grader, or agricultural commodity technician who is knowledgeable in the lay out and operation of the grain elevator and able to identify potentially hazardous conditions.

- c. The scope of the walk-through inspection will depend on the size and complexity of the elevator, and the location of the elevator relative to the FGIS onsite laboratory. However, every walk-through inspection must include a general inspection of the primary grain handling areas and known problem areas.
- d. Prompt and appropriate action must be taken if hazardous conditions are found during a walk-through inspection. See FGIS Directive 4790.9, "Policy and Procedures Upon Encountering Hazardous Conditions," for additional information.

NOTE: FGIS is not responsible for the safety and health of non-Federal inspection and weighing personnel. Therefore those persons are not required to comply with FGIS safety and health procedures. Further, FGIS does not have the authority to enforce safety and health rules for employees of private facilities where FGIS employees work.

5. QUESTIONS

Direct any questions concerning this notice to the Policies, Procedures, and Market Analysis Branch (PPMAB) at (202) 720-0228.