

Program Notice

FGIS-PN-03-03

September 5, 2003

WALK-THROUGH SAFETY INSPECTIONS AT GRAIN ELEVATORS

Contents

1.PURPOSE	2
2.EFFECTIVE DATE	2
3.BACKGROUND	2
4.POLICY	2
5. QUESTIONS	3

In accordance with Federal civil rights law and U.S. Department of Agriculture (USDA) civil rights regulations and policies, the USDA, its Agencies, offices, and employees, and institutions participating in or administering USDA programs are prohibited from discriminating based on race, color, national origin, religion, sex, disability, age, marital status, family/parental status, income derived from a public assistance program, political beliefs, or reprisal or retaliation for prior civil rights activity, in any program or activity conducted or funded by USDA (not all bases apply to all programs). Remedies and complaint filing deadlines vary by program or incident.

Persons with disabilities who require alternative means of communication for program information (e.g., Braille, large print, audiotope, American Sign Language, etc.) should contact the responsible Agency or USDA's TARGET Center at (202) 720-2600 (voice and TTY) or contact USDA through the Federal Relay Service at (800) 877-8339. Additionally, program information may be made available in languages other than English.

To file a program discrimination complaint, complete the USDA Program Discrimination Complaint Form, AD-3027, found online at [How to File a Program Discrimination Complaint](#) and at any USDA office or write a letter addressed to USDA and provide in the letter all of the information requested in the form. To request a copy of the complaint form, call (866) 632-9992. Submit your completed form or letter to USDA by: (1) mail: U.S. Department of Agriculture, Office of the Assistant Secretary for Civil Rights, 1400 Independence Avenue, SW, Washington, D.C. 20250-9410; (2) fax: (202) 690-7442; or (3) email: program.intake@usda.gov.

USDA is an equal opportunity provider, employer, and lender.

1. PURPOSE

The purpose of this notice is to clarify the Federal Grain Inspection Service (FGIS) policy regarding walk-through safety inspections at grain elevators.

2. EFFECTIVE DATE

This action is effective upon receipt

3. BACKGROUND

It is FGIS policy to provide a safe and healthful work environment for all its employees, and to eliminate employee exposure to existing and potentially hazardous working conditions. Accordingly, FGIS employees routinely conduct walk-through safety inspections at grain elevators where FGIS provides onsite service. The purpose of these inspections is to identify and correct hazardous conditions in a timely manner.

4. POLICY

- a. FGIS representatives¹, designated by the local field office manager, must conduct walk-through safety inspections at grain elevators served by the local field office, at least once during each workday; i.e., a day in which FGIS employees are providing onsite inspection/weighing services at the elevator.
- b. During walk-through inspections, the grain elevators must be checked for those conditions that may pose a safety risk to FGIS personnel, including:
 - (1) Fires (including persons smoking), smoldering grain, or visible smoke,
 - (2) Toxic chemical spills,
 - (3) High concentrations of suspended or accumulated dust,
 - (4) Welding, torch cutting, or other hot work,
 - (5) Compressed air being used to remove dust from walls and other areas,
 - (6) Bearings on bucket elevators running hot, slipping belts, and choked legs,
 - (7) Unapproved electrical equipment, loose or damaged electrical conduits, frayed wires, and electrical sparking, and
 - (8) Hazardous walkways, inadequate lighting, defective ladders and stairs, missing guard rails, blocked stairways, and any other potentially hazardous condition.

¹ FGIS supervisor, collateral duty safety and health officer, agricultural commodity grader, or agricultural commodity technician who is knowledgeable in the lay out and operation of the grain elevator and able to identify potentially hazardous conditions.

- c. The scope of the walk-through inspection will depend on the size and complexity of the elevator, and the location of the elevator relative to the FGIS onsite laboratory. However, every walk-through inspection must include a general inspection of the primary grain handling areas and known problem areas.
- d. Prompt and appropriate action must be taken if hazardous conditions are found during a walk-through inspection. See FGIS Directive 4790.9, "Policy and Procedures Upon Encountering Hazardous Conditions," for additional information.

NOTE: FGIS is not responsible for the safety and health of non-Federal inspection and weighing personnel. Therefore those persons are not required to comply with FGIS safety and health procedures. Further, FGIS does not have the authority to enforce safety and health rules for employees of private facilities where FGIS employees work.

5. QUESTIONS

Direct any questions concerning this notice to [AMS - FGIS Policies Procedures and Market Analysis Branch](#).